



# Technical Memorandum

## Reconnaissance-Level Geologic Hazard Assessment

1107 6<sup>th</sup> Street Southeast  
Bandon, Oregon 97411

May 29, 2022

*Prepared for:*

**Berry, Michael C.**  
1107 6<sup>th</sup> Street SE  
Bandon, Oregon 97411

**C/O Sheri McGrath**  
Coos Curry Consulting  
PO Box 1548  
Bandon, Oregon 97411

*Prepared by:*



PO Box 14488  
Portland, Oregon 97293  
T. 503-452-5561 E. ENW@EVREN-NW.com

Project No. 959-22001-01

---

---

# Technical Memorandum

## Reconnaissance-Level Geologic Hazard Assessment

1107 6th Street SE  
Bandon, Oregon 97411

*Prepared for:*

**Berry, Michael C.**  
1107 6<sup>th</sup> Street SE  
Bandon, Oregon 97411

**C/O Sheri McGrath**  
Coos Curry Consulting  
PO Box 1548  
Bandon, Oregon 97411

*By:*



EXP. 2/1/2023

*L.D.G.*

---

Lynn D. Green, C.E.G., Principal Engineering Geologist



*AP 5-1-23*

*Paul M. Trone*

---

Paul M. Trone, R.G., Principal Geologist

## Contents

<b>1.0</b>	<b>INTRODUCTION.....</b>	<b>1</b>
1.1	Purpose .....	1
1.2	Scope.....	1
1.3	Site Description .....	1
<b>2.0</b>	<b>SITE SETTING.....</b>	<b>2</b>
2.1	Topography/Geomorphology .....	2
2.2	Hydrology.....	2
2.3	Geology .....	2
2.4	Hydrogeology/Ground Water .....	3
<b>3.0</b>	<b>POTENTIAL GEOLOGIC HAZARDS.....</b>	<b>3</b>
3.1	Aseismic Hazards.....	3
3.1.1	Mass Wasting.....	3
3.1.2	Compressible Soils .....	4
3.1.3	Storm Water .....	4
3.1.4	Flooding.....	4
3.1.5	High Ground Water Table.....	5
3.1.6	Sea Level Rise.....	5
3.1.7	Wind Erosion.....	5
3.2	Seismic Hazards .....	5
3.2.1	Earthquakes .....	5
3.2.1	Liquefaction .....	6
3.2.1	Slope Failure or Lateral Spread.....	6
3.2.2	Amplification of Ground Shaking.....	6
3.3	Tsunamis.....	6
<b>4.0</b>	<b>WETLANDS.....</b>	<b>7</b>
<b>5.0</b>	<b>RECOMENDATIONS.....</b>	<b>7</b>
<b>6.0</b>	<b>LIMITATIONS .....</b>	<b>8</b>

## Figures (after text)

- 1 Site Vicinity Map
- 2 Aerial Photo Map (2022)
- 3 Site Plan
- 4 Coos County Tax Lot Map
- 5a Historically Active Landslides – Shaded Relief Topographic Map
- 5b LIDAR Map
- 5c Landslide Hazard Map
- 6 Flood Insurance Rate Map
- 7a Earthquake Liquefaction Map
- 7b Earthquake Shaking Hazard Map
- 8 Tsunami Inundation Zone
- 9 Wetland Inventory Map

## Appendices

- A Site Photographs
- B Well Logs from Oregon Water Resources Department Database



---

# **Technical Memorandum**

## **Reconnaissance-Level Geologic Hazard Assessment**

**1107 6th Street SE  
Bandon, Oregon 97411**

### **1.0 INTRODUCTION**

This report presents the results of a reconnaissance-level geologic hazard assessment conducted by EVREN Northwest, Inc. (ENW) for a developed residential lot in Bandon, Oregon. The County designation for the for the approximately 1/2-acre property is Tax Lot 2308, T28S R14W 30DA (see Figures 1 and 2). The assessment was limited to the subject property, and findings and recommendations contained in this report are specific to that property. The assessment was conducted in March of 2022.

#### **1.1 Purpose**

The purpose of the investigation was to identify the potential geologic hazards and related issues, if any, associated with the subject property; and to evaluate them relative to the property owner's proposal to construct a 20-foot by 40-foot garage/shop building (garage) on the property and the requirements of the City of Bandon's Hazard Overlay Zone.

#### **1.2 Scope**

The scope of this investigation consisted of a background review, field investigation, analysis of findings, and development of conclusions. The background review included resources in the office library including maps and publications on regional topography, general geology, engineering geology, geologic hazards, and soils. A tax lot map was provided by the County. Relevant on-line information reviewed included available historical aerial and satellite photography, Oregon Department of Geology and Mineral Industries (ODOGAMI), Statewide Landslide Information Database for Oregon (SLIDO), and published geologic reports and maps of the project area. Information sources are cited in the report and referenced at the end of the report. The field investigation consisted of visual observation of landforms and surface features, and examination of subsurface materials exposed in natural exposures.

#### **1.3 Site Description**

The subject property consists of a developed residential lot that is approximately 200-feet long by 100-feet wide and located in the northeast quarter of the southeast quarter of Section 30, Township 28 south, Range 14 west of the Willamette Meridian in Bandon, Oregon (Figures 1 and 2). It is bordered on the east and west by lots developed with single family residences, on the south by 6<sup>th</sup> Street SE, and on the north by the undeveloped drainage corridor of Ferry Creek (see Figures 2 and 3). There are two residences on the subject property. The largest is a single-story rental home with attached garage situated on east-central portion of the lot. The second is a smaller two-story accessory dwelling unit (ADU) located approximately twenty-five feet behind

(north of) the rental home. A driveway on the eastern edge of the property serves the rental home, and a driveway on the western edge serves the ADU. The proposed garage is to be located at the north end of the western driveway and west of the ADU. The portion of the lot to the south of the rental home is lawn and the portion north of the ADU is woodland (see Figure 3 and photographs in Appendix A).

The homes in the area are served by municipal water; however, municipal sanitary and storm sewers are not available. According to the property owner the domestic waste from both residences is routed to an on-site septic tank and gravity fed drainfield system.

## 2.0 SITE SETTING

### 2.1 Topography/Geomorphology

The study area is located on a broad, elevated, marine terrace landform that underlies Bandon and the coastal strip for approximately 10 miles south of Bandon. In the project area the terrace surface has been cut into by Ferry Creek and its tributaries. The southern three-quarters of the subject property is relatively flat and approximately 40-feet above mean sea level (amsl). The northern quarter of the property is quite steep and drops into the Ferry Creek drainage. The elevation of Ferry Creek near the subject property was not determined, but based on area topographic maps, it appears to be at least twenty feet lower in elevation than the terrace surface (see Figure 1). As shown on the site plan (Figure 3), the slope break between the flat and sloping ground is immediately adjacent to the north sides of the ADU and the proposed garage.

### 2.2 Hydrology

No surface water features (seeps, streams, ponds, etc.) were observed on the subject property during ENW's March 4, 2022, visit to the site. However, the presence of roadside ditches along 6<sup>th</sup> Street SE and various drainpipes discharging to the Ferry Creek drainage (Figure 3 and Appendix A) suggest that storm water management is an issue during wet seasons of the year. Spring discharge was observed on the slope north of the subject property. Since the boundary of the subject property had not been marked in the field, the distance of the spring from the subject property could not be determined. Water from the spring flowed downslope to a marsh area that covers the southern portion of the broad the Ferry Creek drainage. The main channel of the creek appeared to be on the far (north) side of the drainage.

### 2.3 Geology

**Regional:** Beaulieu and Hughes (1975)<sup>1</sup> map the entire coastal strip extending 10 miles south of Bandon and the Coquille River and 2 to 4 miles east from the Pacific shoreline as being underlain by Quaternary marine terrace deposits consisting of "unconsolidated to semi-consolidated flat-lying and elevated marine deposits of sand, silt, clay, and gravel...". These deposits reportedly range in thickness from a few feet to over fifty feet and are typically underlain by bedrock geologic units of Tertiary age. The bedrock unit in the Bandon area is identified by Beaulieu and Hughes as the Roseburg Formation, which they describe as rhythmically bedded hard sandstone and

---

<sup>1</sup> Beaulieu, J. D., and Hughes, P. W., 1975, Environmental geology of western Coos and Douglas Counties, Oregon: Oregon Department of Geology and Mineral Industries Bulletin 87, 148 p., scale 1:62,500.

siltstone with associated marine basalts.

**Site:** The surface geology of the subject property is mapped by Beaulieu and Hughes as Quaternary marine terrace deposits (described above). ENW reviewed water supply well reports (well logs) for two domestic water wells reported to have been completed in the same quarter section (160-acre area) as the subject property and on file in the Oregon Water Resources Department (OWRD) well log data base (GRID database). Copies of these well logs are in Appendix B. These well logs indicate that the terrace deposits are approximately 20- to 25-feet thick and consist primarily of fine to medium gravel and sand. The natural land surface in the developed portion of the subject property has been modified by development related activities, and the undeveloped portion of the property is covered with dense vegetation. Surface soils in roadside ditches and other exposed areas on and near the subject property consist of medium-stiff to stiff silts and sandy silts. Soil (sediment) exposed at and downstream of the spring (approximately 10- to 15-feet lower in elevation than the terrace surface) consists of loose sandy gravel. (See Appendix A).

## 2.4 Hydrogeology/Ground Water

Well logs (Appendix B) indicate that ground water is present in the marine terrace deposits. Static water levels reported on the two well logs reviewed by ENW are 16' below ground surface (bgs) and 12.8' bgs. This shallow ground water is recharged by the infiltration and downward percolation of incident precipitation, and discharges naturally to seeps and springs or as underflow to streams and other surface water features. Ground water can also be withdrawn by wells. The spring observed north of the subject property is likely the result of ground water discharge from the terrace deposits.

## 3.0 POTENTIAL GEOLOGIC HAZARDS

### 3.1 Aseismic Hazards

#### 3.1.1 Mass Wasting

Mass wasting includes all forms of down slope movement of soil and rock material under the influence of gravity. It includes everything from barely perceptible soil creep to catastrophic mud flows and landslides. Steep slopes, weak soil and rock strength, and the various effects of water on soil and rock are the primary controlling factors for mass wasting. The potential for mass wasting can be increased by adding weight to the top of a slope or excavating soil from the lower portion of a slope. Also, earthquakes often serve as triggers for mass wasting events. The flat-lying, unconsolidated to semi-consolidated terrace deposits that underlie the subject property are relatively stable, unless they are exposed on steep slopes or in the sea cliff. As noted above, the northern portion of the subject property is quite steep, with slopes ranging from 30% to more than 100%. No fresh scarps or other evidence of active or recently active landslides or slumps was observed. However, evidence indicative of past mass wasting (hummocky topography and bowed tree trunks) was observed (see Appendix A). No exposures of bedrock were observed on the subject property. However, it is anticipated that bedrock is present 20- to 30-feet beneath unconsolidated terrace sediments mapped at the surface of the site.

Mass wasting events have been mapped within the immediate area of the subject site (Figure 5a and 5b), and the State has indicated that the landslide susceptibility hazard is low to moderate on the flat-lying southern portion of the site and high to very high on the steeply sloping northern portion of the site (Figure 5c).

- It is anticipated that the load created by construction of a 20' by 40' garage at the proposed location on the northern portion of the subject property would increase the potential for mass wasting.

### 3.1.2 Compressible Soils

No surface evidence of highly compressible soils commonly associated with perennial wetlands or bogs was noted on the subject property during the site visit. Poorly compacted, and locally wet soils were noted along and north of the topographic break in slope on the northern portion of the site, and wetlands and standing water were observed in the Ferry Creek drainage north of the site. It is anticipated that seasonal heavy rains in the project area may result in temporary flowing or standing water on portions of the property, so appropriate storm water management (see following section) may be required if the proposed garage is constructed.

- Weak or somewhat compressible soils may be encountered beneath or adjacent to the northern edge of the proposed garage.

### 3.1.3 Storm Water

Given the high anticipated annual rainfall in the project area, storm water management will be a critical element of any site construction project. All storm water run-off from natural surfaces and developed areas (driveways, parking areas, roof gutter down spouts, footing drains, etc.) must be managed in such a way as to prevent surface ponding, flooding of crawl spaces, and excessive erosion or sedimentation. Blocked or broken drain lines or ditches and saturated soils are frequently contributing factors to severe erosion, mass wasting, localized flooding, and foundation settlement. For example, stormwater discharging from the drainpipes currently observed in the slope north of the ADU has the potential to raise the soil moisture content and lead to mass wasting.

### 3.1.4 Flooding

Given the elevation and topographic setting of the subject property, the potential for seasonal, area-wide stream or tidal flood events is very unlikely. A Flood Insurance Rate Map from Federal Emergency Management Agency is attached (Figure 6) showing the entire subject property is outside of the 1% annual chance (100-year) flood plain.

- The exact elevation of the property and the predicted elevations of periodic seasonal flood events (annual, 10-year, 100-year, etc.) in the project area were not established as part of this assessment. Field observations indicate that there is little potential for aerially extensive seasonal or periodic flooding. Flooding of any portion subject property by seismically generated tsunamis is low. This possibility is discussed further in section 3.3.

### 3.1.5 High Ground Water Table

Based on well construction reports for area wells, the uppermost regional ground-water table beneath the project area is likely greater than five feet bgs.

### 3.1.6 Sea Level Rise

According to National Research Council projections<sup>2</sup>, a change in sea level ranging from -4 cm (-2 in) to +23 cm (9 in) is projected by the year 2030 along the northern coast of California (north of Cape Mendocino), Oregon, and Washington. Similar projections along the same section of coastline range from -3 cm (-1 in) to +48 cm (19 in) by the year 2050, and +10 cm (4 in) to +143 cm (56 in) by the year 2100.

- The developed portion of the subject property is approximately 40-feet amsl (based on USGS mapping, see Figure 1), so even a dramatic rise in sea level will not adversely affect the proposed project.

### 3.1.7 Wind Erosion

The entire site is developed or covered with vegetation and no loose soils subject to wind erosion were observed.

- Efforts should be made to limit the removal of or damage to vegetation during construction, and any bare areas of loose soil resulting from construction should be planted with grass or otherwise protected from wind or water erosion.

## 3.2 Seismic Hazards

### 3.2.1 Earthquakes

Beaulieu and Hughes (1975)<sup>1</sup> state that geologic evidence for earthquake activity in western Coos and Douglas Counties is ambiguous and historical data are limited; however, the possibility of future faulting of undefined magnitude remains. In the past three decades, geologists have determined that the Northwest is subject to infrequent, but very powerful (magnitude 9+ on the Richter Scale) subduction zone earthquakes on the offshore Cascadia Subduction Zone (CSZ) fault system<sup>3</sup>. The most recent subduction zone earthquake known to have occurred in the Northwest was in January of 1700.

- Geologists have determined that very large subduction zone earthquakes occur on a 300- to 500-year recurring basis, and that smaller, but still significant, subduction related earthquakes occur on a much more frequent basis.

---

<sup>2</sup> National Academy of Sciences, National Academy of Engineering, Institute of Medicine, and National Research Council, 2012, Sea-Level Rise for the Coasts of California, Oregon, and Washington: Past, Present, and Future, Report in Brief, <http://dels.nas.edu/resources/static-assets/materials-based-on-reports/reports-in-brief/sea-level-rise-brief-final.pdf>

<sup>3</sup> Priest, G.A., 1995, Explanation of Mapping Methods and Use of the Tsunami Hazard Maps of the Oregon Coast: State of Oregon Department of Geology and Mineral Industries Open-File Report O-95-67, 20 p, figures, tables, and appendices.

### 3.2.1 Liquefaction

No subsurface exploration or testing was completed by ENW for this project; however, saturated fine-sandy soils were reportedly encountered during construction of some area wells. These materials are known to have a high liquefaction risk. Earthquake liquefaction hazard is moderate at the subject site (Figure 7a).

### 3.2.1 Slope Failure or Lateral Spread

The effect on slope stability in the project area is difficult to predict. Evidence of mass wasting was observed on the subject property and has been mapped onto the northeast corner of the site (Figures 5a and 5b) and the State has indicated that the landslide hazard is low to moderate on the flat-lying southern portion of the site and high to very high on the steeply sloping northern portion of the site (Figure 5c). The occurrence of a major subduction zone earthquake will certainly increase the likelihood of mass wasting on the northern portion of the site.

- It is anticipated that the load created by construction of a 20' by 40' garage at the proposed location on the northern portion of the subject property would increase the potential for mass wasting.

### 3.2.2 Amplification of Ground Shaking

The subject site is within the area of the state where peak ground accelerations of 55% of gravity can inflict considerable damage in specially designed structures and great damage in ordinary structures during an earthquake occurring once in every 1,000 years<sup>4</sup>. Earthquake shaking potential at the site and surrounding area is expected to be severe (Figure 7b).

- We recommend quantifying the severity of ground motions at the site and/or designing the home to prevent collapse during a worst-case scenario to minimize injury and/or loss of life to the structure's occupants.

## 3.3 Tsunamis

Tsunamis are seismically generated sea waves that typically cause catastrophic flooding when they strike coastal areas. Major earthquakes that occur anywhere in the Pacific Basin have the potential to generate a tsunami that could impact the project area. However, the greatest threat is from an earthquake occurring along the Cascadian Subduction Zone (CSZ), located just offshore of the Pacific Northwest coastline. The magnitude of the earthquake and its resultant tsunami are primarily driven by the amount and geometry of the slip that takes place when the North American Plate snaps westward over the Juan de Fuca Plate during a CSZ event.

DOGAMI's tsunami inundation map<sup>5</sup> (Figure 8) displays the output of its computer models representing five (5) selected tsunami scenarios (S, M, L, XL and XXL), all of which include the earthquake-produced subsidence and the tsunami-amplifying effects of the splay fault, which roughly parallels the CSZ. This model predicts that the subject site is largely outside the area that would be inundated by a tsunami under the less frequent L, XL and XXL scenarios, which

---

<sup>4</sup> Madin, I. P. and Mabey, M. A., 1996, Earthquake Hazard Maps for Oregon: Geological Map Series GMS-100, issued by the State of Oregon Department of Geology and Mineral Industries.

<sup>5</sup> DOGAMI. 2012. Local Source (Cascadia Subduction Zone) Tsunami Inundation Map. Tsunami Inundation Map Coos-16.



correspond to an approximate magnitude 9.1 earthquake. It has been just over 300 years since the last CSZ event. Based on modeling by the State, the maximum wave elevation generated by an “L” event would be about 50 feet, and nearly 80 feet by an XXL event. The estimated time required to generate the energy necessary for L and XXL events is greater than 650 years. The estimated time required to generate the energy necessary for smaller events (S and M) is 300 years or more.

- Based on the State’s models, only the furthestmost northern reaches, i.e., lowest elevation part of the slope, of the subject site would potentially be impacted by an XXL event, which is estimated to take up to 1200 years to accumulate enough energy to generate this size of an event.

#### 4.0 WETLANDS

Based on information provided by Coos County and the US Fish and Wildlife Service, there are no inventoried wetlands on the subject property (Figure 9). Based on ENW’s observations, there are significant wetland areas in the Ferry Creek drainage north of the site.

#### 5.0 RECOMENDATIONS

Based on the work completed for this assessment and the findings discussed above, ENW makes the following recommendations:

- If the location of the proposed garage cannot be moved at least 25’ back (south) from the break in slope, the services of a geotechnical engineer should be used in designing the foundation for that structure.
- Storm water run-off, including downspout and footing drain discharge, from any structure constructed on the property should be managed in a way to prevent ponding, flooding, or excessive erosion or sedimentation. Existing and new drainpipes should be routed away from the sloping northern portion of the property or extended beyond the northern property boundary and to the Ferry Creek drainage.
- Efforts should be made to limit the removal of or damage to vegetation during construction, and any bare areas of loose soil resulting from construction should be planted with grass or otherwise protected from wind or water erosion.
- It is possible that the furthestmost northern reaches of the subject property could be inundated by a less frequent XXL tsunami scenario generated by a 9.1 or greater magnitude earthquake along the CSZ. The owner of the subject property should be aware of and prepared for such an event. There are many helpful emergency preparation and planning resources particularly designed for tsunami response, to name a few:
  - Oregon Office of Emergency Management Tsunami Information, Mitigation & Recovery, Operations and Preparedness;<sup>6</sup>

---

<sup>6</sup> [https://www.oregon.gov/OMD/OEM/Pages/plans\\_train/tsunamis.aspx](https://www.oregon.gov/OMD/OEM/Pages/plans_train/tsunamis.aspx)

- NVS Tsunami Evacuation Zones Map, Brochures, Warnings, Planning;<sup>7</sup>
- ODOGAMI, Oregon Tsunami Clearinghouse: Evacuation Zone Map Viewer, Evacuation Brochures, Regulatory Maps;<sup>8</sup>
- NOAA, National Tsunami Warning Center;<sup>9</sup> and,
- Coos County, Emergency Management.<sup>10</sup>

## 6.0 LIMITATIONS

The scope of this Technical Memorandum is limited to observations made during on-site work; interviews with knowledgeable sources; and review of readily available published and unpublished reports and literature. As a result, these conclusions are based on information supplied by others as well as interpretations by qualified parties.

No subsurface exploration has been performed in conjunction with this assessment, and detailed mapping has not been completed. Figures and findings presented herein are based on limited site reconnaissance. Conclusion and recommendation presented in this assessment were prepared in accordance with generally accepted professional geologic engineering principals and practice. We make no warranty, either express or implied.

We have performed our services for this project in accordance with our agreement and understanding with the Client. This document and the information contained herein have been prepared solely for the use of the Client. We have performed this study under a limited scope of services per our agreement. It is possible, despite the use of reasonable care and interpretation that we may have failed to identify the presence of geological hazards other than those specifically mentioned in this assessment. We assume no responsibility for conditions that we did not specifically evaluate, or conditions that were not generally recognized at the time this report was prepared.

---

<sup>7</sup> <http://nvs.nanoos.org/TsunamiEvac>


<sup>8</sup> <http://www.oregongeology.org/tsuclearinghouse/>

<sup>9</sup> <http://wcatwc.arh.noaa.gov/>


<sup>10</sup> <http://www.co.coos.or.us/Departments/SheriffsOffice/EmergencyManagement.aspx>



# FIGURES



Name: BANDON  
Date: 03/02/22



Location: 043° 06' 58.1186\" N, 124° 23' 47.2347\" W  
Contour Interval: 40 ft




Date Drawn: 3/15/2022  
CAD File Name: 959-22001-01\_fig1sv\_map  
Drawn By: CLR  
Approved By: LDG

Residential Property  
1107 6<sup>th</sup> Street SE  
Bandon, Oregon


## Site Vicinity Map

Project No.  
959-22001  
Figure No.  
**1**






Name: Satellite Image  
Date: 03/02/22



Location: 043° 06' 58.1186\" N, 124° 23' 46.8714\" W

	<p>Date Drawn: 3/15/2022 CAD File Name: 959-22001-01_fig2aerial Drawn By: CLR Approved By: LDG</p>	<p>Residential Property 1107 6<sup>th</sup> Street SE Bandon, Oregon</p>	<p><b>Aerial Photo Map</b></p>	<p>Project No. 959-22001 Figure No. <b>2</b></p>
--	--	--	--------------------------------	--





**LEGEND:**

	SUBJECT BUILDINGS		NEW CONCRETE
	SUBJECT PROPERTY BOUNDARIES		TREE
	ESTIMATED 2-FOOT CONTOURS BASED ON SURFACE MODELING USING DOGAMI LIDAR DATA		
	BREAK IN SLOPE		
	FIRE PIT		

ADU = ACCESSORY DWELLING UNIT

**NOTES:**

1. BASE MAP DEVELOPED FROM AN AERIAL PHOTOGRAPH MAP DATED 2022 AND ENW FIELD NOTES.
2. ALL BUILDING, STREET, AND FEATURE LOCATIONS ARE APPROXIMATE.
3. SYMBOLS REPRESENT LOCATION AND DO NOT ALWAYS REPRESENT EXACT SHAPE, SIZE, OR ORIENTATION.

APPROXIMATE SCALE

environmental, natural resource consultants

PO BOX 14488, PORTLAND, OREGON 97293  
P: (503)452-5561, E: ENW@EVREN-NW.COM

**FIGURE 3**  
**SITE PLAN**  
RESIDENTIAL PROPERTY  
1107 6TH STREET SE  
BRANDON, OREGON



THIS MAP WAS PREPARED FOR  
ASSESSMENT PURPOSE ONLY


NE1/4 SE1/4 SEC.30 T28S R14W W.M.  
COOS COUNTY

1" = 100'

SEE MAP 28S 14W 30AD

28S 14W 30DA  
BANDON

CANCELLED NO.



- 6402
- 6200
- 6900
- 7000
- 7100
- 2802
- 2500
- 3500
- 7301
- 4800
- 2801
- 3100
- 2701
- 7205
- 6401
- 3300

SEE MAP 28S 14W 30DB

SEE MAP 28S 14W 29C



Date Drawn: 3/15/2022  
 CAD File Name: 959-22001-01\_fig4TaxLot  
 Drawn By: CLR  
 Approved By: LDG


Residential Property  
 1107 6th Street SE  
 Bandon, Oregon


### Tax Lot Map




Project No.  
959-22001


Figure No.

**Landslide Inventory (areas and points; various sources)**

Scarp  


Head Scarp  


Deposits  
 Telus-Colluvium  
 Fan  
 Landslide




Date Drawn: 3/15/2022  
 CAD File Name: 959-22001-01\_fig5a\_HistActLands(v01)  
 Drawn By: CLR  
 Approved By: LDG

Residential Property  
 1107 6<sup>th</sup> Street SE  
 Bandon, Oregon

**Historically Active  
 Landslide Map**

Project No.  
 959-22001  
 Figure No.  
**5a**




Date Drawn: 3/15/2022  
 CAD File Name: 959-22001-01\_fig5b\_Lidar(v01)  
 Drawn By: CLR  
 Approved By: LDG

Residential Property  
 1107 6<sup>th</sup> Street SE  
 Bandon, Oregon

**LiDAR Map**

Project No.  
 959-22001  
 Figure No.  
**5b**



Date Drawn: 3/15/2022  
 CAD File Name: 959-22001-01\_fig5c\_LandsSus(v01)  
 Drawn By: CLR  
 Approved By: LDG

Residential Property  
 1107 6<sup>th</sup> Street SE  
 Bandon, Oregon

## Landslide Susceptibility Map

Project No.  
 959-22001  
 Figure No.  
**5c**





Date Drawn: 3/15/2022  
 CAD File Name: 959-22001-01\_fig6\_Flood insuranceMap(v01)  
 Drawn By: CLR  
 Approved By: LDG

Residential Property  
 1107 6<sup>th</sup> Street SE  
 Bandon, Oregon


**Flood Insurance  
 Rate Map**


Project No.  
 959-22001  
 Figure No.  
**6**

**Earthquake Hazard**

Earthquake Liquefaction (Soft Soil) Hazard

- High ■
- Moderate ■
- Low ■




	Date Drawn: 3/15/2022 CAD File Name: 959-22001-01_fig7A_EarthquakeLiquifactionMap(v01) Drawn By: CLR Approved By: LDG	<b>Residential Property</b> 1107 6 <sup>th</sup> Street SE Bandon, Oregon	<b>Earthquake Liquefaction Map</b>	Project No. 959-22001
				Figure No. 7a

**Earthquake Hazard**

Expected Earthquake Shaking

- Violent
- Severe
- Very Strong
- Strong
- Moderate
- Light




Date Drawn: 3/15/2022  
 CAD File Name: 959-22001-01\_fig7b\_Earthquake ShakingMap(v01)  
 Drawn By: CLR  
 Approved By: LDG

Residential Property  
 1107 6<sup>th</sup> Street SE  
 Bandon, Oregon

**Earthquake Shaking Hazard Map**

Project No. 959-22001  
 Figure No. **7b**






Date Drawn: 3/15/2022  
 CAD File Name: 959-22001-01\_fig7a\_TsunamiZoneMap(v01)  
 Drawn By: CLR  
 Approved By: LDG

Residential Property  
 1107 6th Street SE  
 Bandon, Oregon

# Tsunami Inundation Zone Map

Project No.  
 959-22001  
 Figure No.  
 8



- Wetlands**
- Estuarine and Marine Deepwater
  - Estuarine and Marine Wetland
  - Freshwater Emergent Wetland
  - Freshwater Forested/Shrub Wetland
  - Freshwater Pond
  - Lake
  - Other
  - Riverine

	<p>Date Drawn: 3/15/2022          CAD File Name: 959-22001-01_fig8_WetlandInvMap(v01)          Drawn By: CLR          Approved By: LDG</p>	<p>Residential Property          1107 6<sup>th</sup> Street SE          Bandon, Oregon</p>	<p><b>Wetland Inventory          Map</b></p>	<p>Project No.          959-22001          Figure No.  <b>9</b></p>
---	--	--	--	---

APPENDIX A  
SITE PHOTOGRAPHS





Driveway for ADU on west side of subject property looking north from 6<sup>th</sup> Street SE. Rental house in center-right of photo.



ADU located behind (north of) rental home – looking northeast from western driveway.



Driveway for rental house on the east side of the property looking north from 6<sup>th</sup> Street SE along east boundary of subject property.



Proposed site of garage/shop building – looking north from the driveway on the west side of the property.



Residential Property  
1107 6<sup>th</sup> Street SE  
Bandon, Oregon

## Site Photographs

Project No.  
959-22001-01

Appendix  
**A**





Proposed garage/shop building site – looking southeast.



Looking west-northwest from near the northeast corner of the ADU.  
Note bowed trees lower right.



Looking west at the steep slope along the north side of the ADU.



Looking south (uphill) from a position near the northeast property corner.



Residential Property  
1107 6<sup>th</sup> Street SE  
Bandon, Oregon

## Site Photographs

Project No.  
959-22001-01

Appendix  
**A**





Looking west from a position near the northeast property corner.



Masonry block foundation on north side of rental house – view east.



Looking south-southeast at north edge of patio slab near the northwest corner of the ADU.



Masonry block foundation on west side of rental house – view south.



Residential Property  
1107 6<sup>th</sup> Street SE  
Bandon, Oregon

### Site Photographs

Project No.  
959-22001-01

Appendix  
**A**





Drainpipes (center and upper left) discharging to slope. Vertical post in upper right is on east boundary of subject property.



Gravel exposed downslope from spring.



Spring discharging from slope north of ADU.



Looking south along Ohio Street – Ferry Creek drainage in the middle ground, which drainage is north of the subject site.



Residential Property  
1107 6<sup>th</sup> Street SE  
Bandon, Oregon

## Site Photographs

Project No.  
959-22001-01

Appendix

**A**





Looking west from Ohio Street toward Ferry Creek drainage; the subject property backs up to this drainage.

	Residential Property 1107 6 <sup>th</sup> Street SE Bandon, Oregon	<b>Site Photographs</b>	Project No. 959-22001-01 Appendix <b>A</b>
---	--	-------------------------	---

APPENDIX B  
MONITORING WELL AND GEOTECHNICAL HOLE  
REPORTS

STATE OF OREGON WATER SUPPLY WELL REPORT

SEP - 6 1996

WELL ID. # LC7154

(START CARD) # 93070

(as required by ORS 537.765)

WATER RESOURCES DEPT.

Instructions for completing this report are on the last page of this form.

SALEM, OREGON

(1) OWNER: Well Number 455

Name H.F. Sawyer
Address PO Box 1412
City Bandon State OR Zip 97411

(2) TYPE OF WORK
New Well Deepening Alteration (repair/recondition) Abandonment

(3) DRILL METHOD:
Rotary Air Rotary Mud Cable Auger Other

(4) PROPOSED USE:
Domestic Community Industrial Irrigation
Thermal Injection Livestock Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval Yes No Depth of Completed Well 21 ft.
Explosives used Yes No Type Amount

Table with columns for HOLE and SEAL, including Diameter, From, To, Material, and Sacks or pounds.

How was seal placed: Method A B C D E
Backfill placed from ft. to ft. Material
Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER: Table with columns for Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded.

Final location of shoe(s)

(7) PERFORATIONS/SCREENS: Table with columns for From, To, Slot size, Number, Diameter, Tele/pipe size, Casing, Liner.

(8) WELL TESTS: Minimum testing time is 1 hour

Table for well tests with columns for Pump/Bailer/Air, Yield gal/min, Drawdown, Drill stem at, Time.

Temperature of water 53° Depth Artesian Flow Found
Was a water analysis done? Yes By whom
Did any strata contain water not suitable for intended use? Too little
Salty Muddy Odor Colored Other
Depth of strata:

(9) LOCATION OF WELL by legal description:
County COOS Latitude Longitude
Township 28 N or S Range 14 E of W. WM.
Section 30 NE 1/4 SE 1/4
Tax Lot 5403 Lot Block Subdivision
Street Address of Well (or nearest address) 1032 Laurel Street SE
(Washington) Bandon OR

(10) STATIC WATER LEVEL:
16 ft. below land surface. Date 9/3/96
Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:
Depth at which water was first found 16 - 20

Table for water bearing zones with columns for From, To, Estimated Flow Rate, SWL.

(12) WELL LOG:
Ground Elevation +1-300'

Table for well log with columns for Material, From, To, SWL.

Date started 9/3/96 Completed 9/4/96

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
Signed Bandon Well + Pump Co Date
WWC Number

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
Signed Joe Mack Sr. MGCW Date 9/5/96
WWC Number 1493

STATE OF OREGON  
WATER SUPPLY WELL REPORT

(as required by ORS 537.765)

Instructions for completing this report are on the last page of this form.

28-14-30  
WELL I.D. # L 69434  
START CARD # 164010

(1) LAND OWNER  
Name John Ebel Well Number 996  
Address 1052X 1164  
City Bandon State OR Zip 97411

(2) TYPE OF WORK  
 New Well  Deepening  Alteration (repair/recondition)  Abandonment

(3) DRILL METHOD:  
 Rotary Air  Rotary Mud  Cable  Auger  
 Other \_\_\_\_\_

(4) PROPOSED USE:  
 Domestic  Community  Industrial  Irrigation  
 Thermal  Injection  Livestock  Other \_\_\_\_\_

(5) BORE HOLE CONSTRUCTION:  
Special Construction Approval  Yes  No Depth of Completed Well 267 ft  
Explosives used  Yes  No Type \_\_\_\_\_ Amount (100)

HOLE			SEAL			Sacks or pounds
Diameter	From	To	Material	From	To	
10"	0	26	Bentonite	0	19	13 SX

How was seal placed: Method  A  B  C  D  E  
 Other Poured from surface  
Backfill placed from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Material \_\_\_\_\_  
Gravel placed from 19 ft. to 26 ft. Size of gravel 10/20

(6) CASING/LINER:

Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing: 5"	+1	21'7"	160#	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6"	+14	4'	250	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<u>(Protective Casing)</u>							
Liner:				<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Drive Shoe used  Inside  Outside  None  
Final location of shoe(s) \_\_\_\_\_

(7) PERFORATIONS/SCREENS:  
 Perforations Method Attached to casing  
 Screens Type Nyloka V-w Material SS

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
21'7"	26'7"	10/16		5"	Pipe	<input type="checkbox"/>	<input type="checkbox"/>

(8) WELL TESTS: Minimum testing time is 1 hour  
 Pump  Bailer  Air  Flowing  Artesian  
Yield gal/min 10 Drawdown - Drill stem at 25 Time 1 hr.

Temperature of water 52° Depth Artesian Flow Found \_\_\_\_\_  
Was a water analysis done?  Yes By whom BW&S  
Did any strata contain water not suitable for intended use?  Too little  
 Salty  Muddy  Odor  Colored  Other \_\_\_\_\_  
Depth of strata: \_\_\_\_\_

**Bandon Well & Pump Company**

(9) LOCATION OF WELL by legal description:  
County Coos Latitude \_\_\_\_\_ Longitude \_\_\_\_\_  
Township 28 N of S Range 14 E of W. W.M.  
Section 30 SW 1/4 SE 1/4  
Tax Lot 2200 Lot \_\_\_\_\_ Block \_\_\_\_\_ Subdivision \_\_\_\_\_  
Street Address of Well (or nearest address) 87707 Bulls Creek Rd Bandon

(10) STATIC WATER LEVEL:  
12'10" ft. below land surface. Date 8/21/04  
Artesian pressure \_\_\_\_\_ lb. per square inch Date \_\_\_\_\_

(11) WATER BEARING ZONES:  
Depth at which water was first found 12'10"

From	To	Estimated Flow Rate	SWL
12'10"	25	+1-10	12'10"

(12) WELL LOG:  
Ground Elevation +1-300'

Material	From	To	SWL
Top soil	0	2	
Sandy Clay Lt Brown	2	8	
Sand Fine brown	8	12	
Sand F-C w/ Gravel F Brown	12	17	
Sand F-C w/ Gravel F-m Brn	17	19	
Gravel F-m w/ Sand F-C grey	19	22	
Clay Gray sandy	22	23	
Gravel F-C w/ Sand C-F	23	25	
+WOOD			
Sandstone grey	25	26	

**RECEIVED**

AUG 25 2004

WATER RESOURCES DEPT  
SALEM, OREGON

Date started 8/2/04 Completed 8/21/04

(unbonded) Water Well Constructor Certification:  
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.  
Signed \_\_\_\_\_ WWC Number \_\_\_\_\_ Date \_\_\_\_\_

(bonded) Water Well Constructor Certification:  
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.  
Signed Jim Mack Sr Mgr WWC Number 1443 Date 8/23/04