

Zoning Compliance Application

Temporary Storage Sheds, Alternative Energy & Simple Additions (under 200 Sq. Feet)

Oregon Law allows the City up to 30 days to review an application to determine whether or not the application is "complete" or "incomplete." Planning staff strives to be responsive and minimize this review period. However, careful and thorough reviews lay a foundation for smoother and quicker subsequent review processes. Please visit the City's

CITY OF BANDON PLANNING P.O. BOX 67 555 HWY 101 BANDON, OR 97411 P:(541) 347-7922 F:(541)347-1415

website for submittal requirements http://www.cityofbandon.org/general/page/welcome-planning-department. Application # SUBMITTAL DATE: _ I. PROJECT LOCATION: HAVE PERMITS BEEN OBTAINED FOR OTHER WORK RELATED TO THIS PROJECT? Street Address: X Yes □No ☐Not Required 2770 Whale Watch Way, Bandon OR Please describe: Permit to repair dry rot and enclose existing covered patio Lot Size: 0.34 acres Map Number / Tax Lot(s): 28S15W36CB/ 606 Zone: CD-1 Floodplain: ☐Yes II. APPLICANT'S INFORMATION (if applicant is not the property owner) Phone: 503.784.5070 Applicant's Name: E-Mail: Linda@moorearchdesign.com Linda Cameron, Moore Architecture + Design, LLC Applicant's Mailing Address: 2327 SW Market Street Dr, Portland, OR III. PROPERTY OWNER'S INFORMATION Phone: 307.733.7644 Property Owner's Name: Central Point Properties, LLC E-mail: dwelch@weimail.com Mailing Address: PO Box 3000, Jackson, WY 83002 III. PROJECT DESCRIPTION: (Please check all that apply) Additions to Building: ☐ Change of Use X Rear ■ New Construction Front □ Alterations Height □Other: ☐Side Yard Present Use: Landscape area Proposed Use (Please describe, include a drawing with exact dimensions, attach sheets of paper as needed): New 158 sf addition to house Sáuna and small entry / shower room. New structure to be 8'-6"wide by 18'-6" long. IV. SITE PLAN: Plans may be submitted electronically; printed copies submitted on paper larger than ledger size (11x17) will not be accepted. Include ALL relevant information pertaining to your proposed project. Please see our "How to

Inspection #1:
Compliance with the approved site plan. Inspection required before setting posts or pouring any concrete.
(Please mark all post or form positions)

Create a Site Plan" document for tips on how to create your site plan.

or complete required inspections may delay the final approval of your project.

Inspection #2:

V. INSPECTION SCHEDULE: All city inspections must be requested at least 2 business days in advance. Failure to schedule

Compliance with approved plans for drainage, height, utility service, off-street parking, any required street improvements, and authorized land use. (Required upon completion of installation)

VI. CONTACT SIGNATURE/AUTHORIZ

I have read the application and the attached documentation and I understand that my application may be delayed or deemed incomplete if I have provided insufficient information and documentation to allow for approval.

I certify that the information provided in this application, including all submittals and attachments, is true and correct to

the best of my knowledge.

I understand and agree that all required inspections will be requested 2 business days in advance, and it is the applicant's responsibility to ensure required inspections have been requested, completed, and approved. I authorize the City of Bandon or its acting agent, to enter onto the subject property, as described in section "I. Project location".

I authorize the following party(s) to act as applicant in regard to the attached application for the subject property described above.

X Property Owner's Signature: Soon Grand A19057 Masser.	Date: Oct 4, 2021
X Applicant's Signature: Ind Man	Date: 10.1.2021

VII. DISCLOSURE:

The City of Bandon is legally obligated to report all ground disturbances within the City of Bandon to the Coquille Indian Tribe. Property owners and applicants must adhere to all conditions and requirements set out by the Coquille Indian Tribe, State Historic Preservation Office (SHPO) or both if required. Please be aware that state statutes and federal law govern how archaeological sites are to be managed. ORS 97.745 prohibits the willful removal, mutilation, defacing, injury, or destruction of any cairn, burial, human remains, funerary objects, or objects of cultural patrimony of a Native Indian. ORS 358.920 prohibits excavation, injury, destruction, or alteration of an archaeological site or object, or removal of an archaeological object from public or private lands.

It is the property owner/applicant's responsibility to determine if additional permits from other agencies will be required, including but not limited to: Oregon State Building Codes, Oregon State Department of Environmental Quality, FEMA, Oregon State Fish and Wildlife and U.S. Fish and Wildlife. If additional permits are required, it is the responsibility of the property owner/applicant to obtain such permits and comply with their conditions of approval.

It is the property owner/applicant's responsibility to provide the City of Bandon all necessary legal documentation related to the property, including but not limited to: receipts, deed restrictions, vacation records, easement records, etc.

I acknowledge, understand, and agree, that all relevant documentation will be provided to the City of Bandon, and that all required permits and consent will be obtained prior to the start of construction, with all conditions of approval adhered to.

Sease Evens	OCT 4, 2021
Property Owner A13652F140834FF.	Date
X Sud Dan	10.1.2021
Applicant's Signature	Date

AN ELECTRONIC COPY OF THIS FORM IS ACCEPTABLE FOR THE PURPOSE OF FILING AN APPLICATION. HOWEVER, THE ORIGINAL WILL BE REQUIRED PRIOR TO FINAL APPROVAL.

Staff's Signature of Intake:	Date:	
Staff's Signature of Approval:	Date:	

Submittal Requirements:

- 1. Completed Pre-Application with summary notes from the Planning Department (if applicable)
- 2. Complete Planning Permit application (including fees and applicable property records)
- 3. Signed Development Disclosure
- 4. Completed Submittal Requirement sheet

	🗵 Setbacks on all sides of the property (must be marked from the closest structure to the property lin	ne)	
	 Property line must be clearly marked on all sides - if property corners cannot be determined a survey will be required. 		
	☑ Location of all buildings and proposed building or addition	-,	
	☑ Location of all mechanical equipment and proposed equipment (HVAC, propane tanks and enclosure)	res - these cannot be located	
	in the setback area)	es these cumot be located	
	☑ Fences, patios, sidewalks, (if being built along with the construction of a building)		
	Decks, steps, porches (these cannot be located in the setback)		
	☑ All off-street parking		
	☑ Location of the front entrance and all exterior doorways		
	 ☑ Location of the front entrance and all exterior doorways ☑ Location & material of the driveway 		
	☑ Direction of roof drainage		
ΙA	☐ Drywell, if required (must be engineered)		
	☑ Location of electric meter base (on the front or no farther than 5 feet down the side)		
JA	Proposed water and sewer line location		
V/N	☐ Water shut off valve must be located beside the water meter box; 6" sewer clean out must be at th		
	Square footage of the lot, structures including garage (1st & 2nd floors noted separately), and percentage of impermeable		
	surface impermeable surfaces written on the plot plan		
	Design Feature Requirements (Please check your selections)		
	Homes in the R-1 and R-2 zones require a minimum of 6 (at least 3 on the face of the home)		
	Homes in the CD zones require a minimum of 8 (at least 4 on the face of the h	ome)	
	☐ Roof pitch at or greater than 3/12	☐ Bay windows	
	☐ Covered porch - (minimum of 25 square feet)	☐ Cupolas	
	☐ Tile or Architectural grade shingles (not composition shingle)	☐ Hip roof	
	☐ Off set of the building face or roof (at least one foot, minimum of 2 feet in cd-1 & cd-2 zones)	☐ Pillars or posts	
	☐ Eaves with a minimum projection of six (6) inches	 Mullioned windows 	
	☐ Horizontal lap siding, cedar shake or shingle on 100% of the exterior	☐ Window shutters	
	☐ Recessed entry area (minimum depth of three feet)	☐ Clerestory windows	
	☐ Garage (constructed with exterior finish materials matching the residence)	☐ Dormers	
	☐ Combination of cedar shake and shingle siding or lap siding with stone	☐ Gables	
	Additional Required Plans		
L			
	☐ Floor plan - Including garage (before and after drawings must be included for remodel/additions)	200 W 200	
	☐ Elevation of all structures - All sides must show direction, dimensions, height, design features and design features are design features and design features and design features are design features are design features are design features.	epth of eaves/gutters.	
	Grade of property and/or grading plan - (if applicable)		
	☐ Foundation plan for all construction - (for a manufactured home the slab & runner system)		
	DEQ septic system permit & plan drawings - (if applicable)		
	☐ Geotechnical report - (if applicable)		
	 □ Drainage plan with engineered drawings - (if applicable) □ Engineered foundation - (if applicable) 		
	I Engineered folingation = (if applicable)		

YOUR APPLICATION <u>WILL</u> BE DEEMED INCOMPLETE IF YOUR SITE PLAN FAILS TO LIST ALL REQUIRED INFORMATION, INCLUDING DESIGN FEATURE REQUIREMENTS WHICH MUST ALSO BE SHOWN IN YOUR SUBMITTED ELEVATION PLANS.

K & A ENGINEERING, INC. 91051 S. WILLAMETTE STREET P. O. Box 8486, Coburg, OR 97408 (541) 684-9399 · KAENGINEERS.COM



September 30, 2021 Project: 21054

Central Point Properties, LLC P. O. Box 3000 Jackson, WY 83022

Subject: Geotechnical Site Evaluation

Sauna Addition

2770 Whale Watch Way, Bandon, Oregon

PURPOSE AND SCOPE

Our understanding is that you are currently considering the addition of a small sauna structure to be located at the south perimeter foundation of the existing residence at the subject project site.

The City of Bandon is requiring a geotechnical assessment of the site prior to permitting. We assume this is to identify any possible geologic hazards that may affect or be affected by the project.

The scope of our services for this project included a site inspection, researching published geology and geologic hazards for the area, and this written report.

SITE EVALUATION

SITE CONDITIONS

The project site is located south of Bandon at the end of a small, paved street (Whale Watch Way) on a level bench that has an elevation approximately 50-feet above the beach. The site descends from the bench with a uniform west-facing slope having an overall gradient of approximately 2.6 H: 1 V (21-deg). Several low retaining walls are located at the top of the slope bordering paths providing beach access. East of the site the grade ascends gradually to another bench.

Except for the building pad and paved patio and walkways, the ground surface has a dense grass cover. The slopes are uniform and regular, showing no indications of slope movement or surface erosion such as cracks, steep scarps, depositional areas, or rills or gullies.

Our examination of aerial photography of the general locality indicates areas of shallow sloughing and slope instability further north of the project site where the bluffs descending to the beach are much steeper and abrupt and dissected with small intermittent drainages. However, these surface conditions do not exist at the project site.

See the Vicinity Map and Project Site Plan and Geologic Section attached to this report.

Geologic Site Evaluation Sauna Addition Project \cdot 2770 Whale Watch Way, Bandon, Oregon September 30, 2021 \cdot K & A Engineering, Inc. \cdot Project No.: 21054



LOCAL GEOLOGY

We observed exposed weathered bedrock outcrops north and south of the project site. Bedrock appears to be a gray, soft, sedimentary rock with the appearance of a siltstone or mudstone conglomerate. Local bedrock geology is mapped as "Melange of Sixes River" (Tertiary) – a mix of sandstones, volcanics, conglomerates, and siltstones.¹

Our observations confirm mapped geology for the area.

MAPPED GEOLOGIC HAZARDS

We reviewed geologic hazard mapping of the area published by the Oregon Department of Geology and Minerals Industries (DOGAMI). Hazards mapped at the site include:

- **Earthquake Ground Motion:** Severe. This is due to proximity to the Cascadia subduction zone.
- Liquefaction: Moderate.
- Landslide Hazard: Low to Moderate (moderate on the ascending east slope).

DOGAMI has mapped one zone of landslide deposits north of the project site – the same area of oversteepened sloughing bluffs that we identified located approximately 500-feet north of the project site.

The Coquille Anticline is located approximately 1.5-miles northeast of the site. This quaternary fault is approximately 27-km long with a strike of N 30-deg W. This reverse fault is mapped as "active" with an estimated slip rate between 0.2 and 1.0-mm/yr. No known historic earthquakes are associated with this fault. Since this fault is not known to be associated with any earthquake activity and the slip rate is less than 1-mm/yr, the site is not considered "near-fault." Ground surface rupture doe to faulting is not likely at the project site.

RECOMMENDATIONS

GEOLOGIC HAZARD MITIGATION

Landslide Hazard

Overall, we found that hazards due to slope movement at the site are low to moderate. This determination is based on the following:

 Modest west descending slope gradient due to the modest slopes and the fact that the foundation for the existing house and the proposed addition is likely either on or very close to

¹ Wiley, McClaughry, Ma, Lina, Mickelson, Niewendorp, Stimely, Herinckx, and Jonathan; Geologic Map of the Southern Oregon Coast between Port Orford and Bandon, Curry and Coos Counties, Oregon. Open-File Report O-2014-01. Oregon Departmenet of Geology and Mineral Industries. 2014.

² ASCE 7-16 Section 11.4.1

Geologic Site Evaluation Sauna Addition Project · 2770 Whale Watch Way, Bandon, Oregon September 30, 2021 · K & A Engineering, Inc. · Project No.: 21054



bedrock. It is unlikely that the descending south slope experience slope movement with the high peak ground accelerations that the design earthquake would present because of the low slope gradient. The east ascending slope likely includes some loose sand which may experience minor sloughing during earthquake loading. However, the distance of the addition and existing house from the toe of the ascending slope provides a good buffer against any debris that may fall from this slope in the event of minor sloughing.

No mitigation is recommended for slope movement hazard at this site.

Severe Earthquake Motion

Large peak ground accelerations are expected on the entire Oregon coast. This hazard should be addressed by incorporating the appropriate horizontal response spectral parameters into the structure's lateral bracing system. Assuming, conservatively, that the site is a site class C (soft rock), we recommend seismic design criteria for the project area as summarized in Table 1. Design to this standard will reasonably address severe ground motion for earthquake ground motion.

Parameter	Design Values	
raiailletei	0.2-Second	1-Second
MCE _R Ground Motion	S _S = 2.039 g	$S_1 = 0.973 \text{ g}$
Site Class	С	
Site Coefficient	F _a = 1.200	F _v = 1.400
Site Modified Spectral Response Acceleration	S _{MS} = 2.477 g	S _{M1} = 1.362 g
0.2-second Design Value	S _{DS} = 1.631 g	$S_{D1} = 0.908 g$
PGA _M (Site Modified Peak Ground Acceleration)	1.218 g	

Table 1 - Seismic Design Criteria

Liquefaction and Lateral Spreading

Due to the shallow nature of bedrock and the lack of saturated loose sands at the project site, there is not a local hazard of earthquake-induced liquefaction of lateral spreading. No mitigation is recommended for liquefaction and lateral spreading.

Coastal Erosion

This section of the Oregon coastline is not mapped for beach regression. However, there is a significant distance between the toe of the west descending slope and the beach (over approximately 200-feet) which is broken up with undulating foredune deposits which are heavily vegetated. Due to the vegetated buffer we recommend that there is not a significant hazard of beach slope regression which would affect stability of the project site.

No mitigation is required for mitigation of beach regression at this site.

Geologic Site Evaluation Sauna Addition Project · 2770 Whale Watch Way, Bandon, Oregon September 30, 2021 · K & A Engineering, Inc. · Project No.: 21054



SUMMARY

We have reviewed the proposed addition project including the nature of the structure and it's proposed location. We have also reviewed known and mapped/published geologic hazard conditions at the site. We have found no unusual or significant geologic hazards that would prevent construction of the project as proposed.

We recommend acceptance of the proposed addition project by the local planning official provided that the structural design incorporate the recommended seismic spectral design criteria of Table 1.

LIMITATIONS AND USE OF GEOTECHNICAL RECOMMENDATIONS

This report has been prepared for the exclusive use of Central Point Properties, LLC for the subject project.

This geotechnical evaluation, analysis, and recommendations meet the standards of care of competent geotechnical engineers providing similar services at the time these services were provided. We do not warrant or guarantee site surface subsurface conditions. Note that our evaluation was made using visual observations and assumptions about subsurface conditions based on local experience and geology. No exploration test holes were made. However, exploration test holes do not necessarily reflect soil/rock materials or groundwater conditions that exist between or beyond exploration locations or limits.

The scope of our services does not include construction safety precautions, techniques, sequences, or procedures, except as specifically recommended in this report. Our services should not be interpreted as an environmental assessment of site conditions.

Thank you for the opportunity to be of service. Please call us if you have questions or need further assistance.

Sincerely,


Michael Remboldt, P.E., G.E.

M Remboldo

K & A Engineering, Inc.

19474 PP 19474 PP OREGON OREGON OF TO DENNIS REMBU

RENEWS: 12/31/2022



K & A Engineering,Inc

91051 S. Willamette St. Coburg, OR 97408 541 684 9399 541 684 9358 fax




VICINITY MAP Geotechnical Site Evaluation Sauna Addition

2770 Whale Watch Way, Bandon, Oregon


9/30/21 Project: 21054 Drawing 1 / 2



RENEWS: 12/31/2022



SITE PLAN



GEOLOGIC SECTION

K & A Engineering,Inc

91051 S. Willamette St. Coburg, OR 97408 541 684 9399 541 684 9358 fax



PROJECT SITE PLAN AND GEOLOGIC SECTION

Geotechnical Site Evaluation
Sauna Addition

2770 Whale Watch Way, Bandon, Oregon

9/30/21 Project: 21054

Drawing 2 / 2

RENEWS: 12/31/2022

19474

ATC Hazards by Location

Search Information

Address: 2770 Whale Watch Way, Bandon, OR 97411, USA

Coordinates: 43.1024616, -124.4324376

Elevation: 23 ft

Timestamp: 2021-09-30T23:16:38.364Z


Hazard Type: Seismic

Reference ASCE7-16

Document:


Risk Category: II Site Class: C

MCER Horizontal Response Spectrum



Sut Coos Bay 23 ft Ros€ Coquille Winsto Муг Car Langlois Port Orford Google Map data ©2021 Google

Design Horizontal Response Spectrum



Basic Parameters

Name	Value	Description
S _S	2.039	MCE _R ground motion (period=0.2s)
S ₁	0.973	MCE _R ground motion (period=1.0s)
S _{MS}	2.447	Site-modified spectral acceleration value
S _{M1}	1.362	Site-modified spectral acceleration value
S _{DS}	1.631	Numeric seismic design value at 0.2s SA
S _{D1}	0.908	Numeric seismic design value at 1.0s SA

▼Additional Information

Name	Value	Description
SDC	E	Seismic design category
Fa	1.2	Site amplification factor at 0.2s
F_{v}	1.4	Site amplification factor at 1.0s
CRS	0.857	Coefficient of risk (0.2s)


CR ₁	0.861	Coefficient of risk (1.0s)
PGA	1.015	MCE _G peak ground acceleration
F _{PGA}	1.2	Site amplification factor at PGA
PGA _M	1.218	Site modified peak ground acceleration
TL	16	Long-period transition period (s)
SsRT	2.039	Probabilistic risk-targeted ground motion (0.2s)
SsUH	2.381	Factored uniform-hazard spectral acceleration (2% probability of exceedance in 50 years)
SsD	3.476	Factored deterministic acceleration value (0.2s)
S1RT	0.973	Probabilistic risk-targeted ground motion (1.0s)
S1UH	1.129	Factored uniform-hazard spectral acceleration (2% probability of exceedance in 50 years)
S1D	1.293	Factored deterministic acceleration value (1.0s)
PGAd	1.448	Factored deterministic acceleration value (PGA)

The results indicated here DO NOT reflect any state or local amendments to the values or any delineation lines made during the building code adoption process. Users should confirm any output obtained from this tool with the local Authority Having Jurisdiction before proceeding with design.

Disclaimer

Hazard loads are provided by the U.S. Geological Survey Seismic Design Web Services.

While the information presented on this website is believed to be correct, ATC and its sponsors and contributors assume no responsibility or liability for its accuracy. The material presented in the report should not be used or relied upon for any specific application without competent examination and verification of its accuracy, suitability and applicability by engineers or other licensed professionals. ATC does not intend that the use of this information replace the sound judgment of such competent professionals, having experience and knowledge in the field of practice, nor to substitute for the standard of care required of such professionals in interpreting and applying the results of the report provided by this website. Users of the information from this website assume all liability arising from such use. Use of the output of this website does not imply approval by the governing building code bodies responsible for building code approval and interpretation for the building site described by latitude/longitude location in the report.



PROJECT INFORMATION

PROJECT ADDRESS 2770 WHALE WATCH WAY

BANDON, OREGON 97411

OWNER

CENTRAL POINT PROPERTIES LLC

P.O. BOX 3000

JACKSON, WY 83002

CONTACT: DIANA WELCH, 307.733.7644

ARCHITECT OF RECORD MOORE ARCHITECTURE + DESIGN, LLC 2327 SW MARKET STREET DRIVE

PORTLAND, OR 97201

CONTACT: LINDA CAMERON, 503.784.5070

ENGINEER OF RECORD RESIDENTIAL ENGINEERING 2689 BOWMAN ROAD

REEDSPORT, OR 97467

CONTACT: SCOTT KENT, 541.707.0015

GENERAL

MORRISON GEDEROS LLC

PO BOX 1225

COOS BAY, OR 97420

CONTACT: STEPHEN GEDEROS, 541.290.858

SUMMARY TABLE

MAP AND TAX LOT: ZONING DISTRICT:

28S15W36CB 606

CD-1 / CONTROLLED DEVELOPMENT 1 ZONE

LOT SIZE:

0.34 ACRES PROVIDED

REQUIRED SETBACKS: FRONT: 15'-0"

15'-4" - EXT'G - NO CHANGE

(PER 17.104.060)

SIDES: 13'-0" 7'-2" + 75' -6"

REAR: 10'-0"

BUILDING HEIGHT: 24'-0"

PROVIDED 10'-0"

13'-7"

LOT COVERAGE:

BUILDING FOOTPRINT:

EXT'G BUILDING: PROPOSED:

3,374 sf 158 sf

EXISTING DECKS: EXISTING IMPREVIOUS 236 sf

SURFACES: PROPOSED:

ACES: 1,065 sf OSED: 0 sf

TOTAL IMPREVIOUS SURFACE:

4833 sf

PROPOSED: 4833/14810=32.6% <50% = ALLOWED

SITE PLAN



View from West (ocean side)

Moore Architecture + Design, LLC

Architecture, Planning, Urban Design

2327 SW Market Street Drive, Portland OR 503.784.5070 / 503.708.3165 email: moorearchdesign.com

Owner: Central Point Properties, LLC Project: Bandon Beach House - Sauna Addition Address: 2770 Whale Watch Way, Bandon, Oregon

Images



View from West (ocean side)


Moore Architecture + Design, LLC

Architecture, Planning, Urban Design

2327 SW Market Street Drive, Portland OR 503.784.5070 / 503.708.3165 email: moorearchdesign.com

Owner: Central Point Properties, LLC Project: Bandon Beach House - Sauna Addition Address: 2770 Whale Watch Way, Bandon, Oregon Image

3



View from Street (back of house)

Moore Architecture + Design, LLC

Architecture, Planning, Urban Design

2327 SW Market Street Drive, Portland OR 503.784.5070 / 503.708.3165 email: moorearchdesign.com

Owner: Central Point Properties, LLC Project: Bandon Beach House - Sauna Addition Address: 2770 Whale Watch Way, Bandon, Oregon

Image